

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



GOI's inter-connected for total project management within one program




Fig. 1



FLOW CHART- GOI Interface program with single point access from inside the program.




Fig. 2



Startup screen when program is loaded




Fig. 3



Typical GOI screen menu with GOI links as seen at start of menu.

Accurate Data Plan Service
102 East Boone, Suite 7
Spokane, Washington 99202
Phone : (509) 399-8305
Fax: (509) 325-3711

Building

Tri State Memorial Hospital
Clarkston, Washington

Plan Item: Air Handlers
Item No: AH-1

(C) → Specification

(B) → Plan Location

(A) → Schedule

(G) → Section


(D) → Submittal



(F) → Details

(H) → Diagnostics

(E) → Operation & Maintenance Manual

Fig. 4







Catalog representations of the actual items to be installed and the specific location as accessed from GOI link (D) shown in Fig. 4.




Fig. 8

OLIO JC76
APR 09 2004
PATENT & TRADEMARK

Maintenance & Operation Manual listing all of the parts and the basic trouble shooting guide of the item as accessed from GOI link (E) shown in Fig. 4.




Fig. 9